

City of Wichita, Kansas
Americans with Disabilities Act Transition Plan
Veterans' Memorial Park

201 South Greenway Blvd.

July 2005



Prepared by

DMCG
Disability Management Consulting Group L.L.C.
2801 Jonquil Place
Columbia, MO 65202

In conjunction with

The Great Plains ADA & IT Center and the City of Wichita Disability Advisory Board

City of Wichita – ADA/504 Transition Plan – Veteran’s Memorial Park - July 2005 Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

| Locations | Structural Inconsistencies | | Recommended Corrections/Modifications to Ensure Program Access | Criteria – L=low, M=medium, H=high | | | Supplemental Technical Information | | | Finalized Actions | | |
|----------------------|------------------------------------------------------------------------------------|---------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|---------------|-----------------|----------------------------------------|------------------|--------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|----------------------|----------------------------------|
| Location | Identified Issue | ADAAG Specifications | Recommended Correction | Priority (overall) | Public Access | Frequency - PWD | Photo # | Conceptual Costs | Support Information | Finalized Correction | Date to be Corrected | Date Completed (Include initial) |
| 1. Drinking Fountain | The faucet control, on the drinking fountain, is not within specified reach range. | 4.15 4.1.3(10) | According to ADAAG, the number of all facilities and elements, which are required to be accessible, are delineated in ADAAG section 4.1 . However, 4.1 only addresses drinking fountains in reference to floors of a building or facility. The program access provisions of Title II require all programs and services to be accessible and usable. Drinking fountains are a service provided by the City and must be made accessible. The number of drinking fountains that are required to be accessible in a park or play area setting is debatable, but we consider that at least one at this particular park should be fully accessible to individuals who use wheelchairs. Modify the existing drinking fountain to comply with ADAAG specifications for individuals who use wheelchairs, including spout height and faucet controls. Additionally, we recommend providing a hi-lo fountain where the existing fountain is located. | L | M | M | 1 | \$300 | Building Block 7 – Drinking Fountains Sample hi-lo fountain in park setting | Provide an ADAAG compliant hi-lo drinking fountain at the current location of the non-compliant fountain. | 12/31/16 | Under Construction |
| 2. Pedestrian Paths | The ramp, leading to the flags, does not provide handrails on each side. | 4.8 | According to ADAAG, any part of an accessible route with a slope greater than 1:20 shall be considered a ramp. If a ramp run has a rise greater than 6-inches or a horizontal projection greater than 72-inches, then it shall have handrails on both sides. The existing path to the flag area is a ramp with surface running slopes greater than 5%. Provide handrails on each side of the ramped surface, which comply with ADAAG. | M ® | H | L | 3 4 | \$750 | Ramp Detail | Provide ADAAG compliant handrails on both sides of the ramp where the slope exceeds 5%. | 12/31/11 | Under Construction |

Veteran's Memorial Park - Conceptual Cost Projections

| | |
|---------------------------|----------------|
| Total | \$1,050 |
| Year Three (High) | \$0 |
| Year Five (Medium) | \$750 |
| Year Ten (Low) | \$300 |