My Map

PARKSTONE EXISTING
SITE CONDITIONS
BASEMENTS WERE LEFT
IN PLACE AND FILLED
W RUBBLE



12000
6240
5000
4500

27740 ¢ APPX. BSMT.
BELOW 8'
8,260 cu yd RANGE

2700 lb. PER cy

20-22 cy. PER LOAD
8260/21cy = 393 LDS.

ices
ations
ita, KS 67203
62.1174
0 2016

DISCLAIMER: It is understood that, while Sedgwick County Geographic Information Services (SCGIS), City of Wichita GIS, (for purposes of the road centerline file), participating agencies, and information suppliers, have no indication or reason to believe that there are inaccuracies in information provided, SCGIS, its suppliers make no representations of any kind, including, but not limited to, warranties of merchantability or fitness for a particular use, nor are any such warranties to be implied with respect to the information, data or service furnished herein. In no event shall the Data Providers become liable to users of these data, or any other party, for any loss or damages, consequential or otherwise including but not limited to time, money, or goodwill, arising from the use, operation or modification of the data. In using these data, users further agrees to indemnify, defend, and hold harmless the Data Providers for any and all liability of any nature arising out of or resulting from the lack of accuracy or correctness of the data, or the use of the data. No person shall sell, give or receive for the purpose of selling or offering for sale, any portion of the information provided herein.